

Appendix B Photographs

List of Photos

Photo 1	Site S1. East Fork Moose Creek (PLMP 1.0). Looking across active channel from right high bank.....	5
Photo 2	Site S1. East Fork Moose Creek (PLMP 1.0). Soil approximately 100 feet from right high bank.	5
Photo 3	Site S1. East Fork Moose Creek (PLMP 1.0). Looking upstream (difficult to see creek through the grass).....	6
Photo 4	Site S1. East Fork Moose Creek (PLMP 1.0). Looking north (upstream at proposed crossing site).....	6
Photo 5	Site S2. Moose Creek (PLMP 3.9). Looking upstream from proposed crossing site.	7
Photo 6	Site S2. Moose Creek (PLMP 3.9). Looking downstream from proposed crossing site.....	7
Photo 7	Site S2. Moose Creek (PLMP 3.9). Looking at right bank.	8
Photo 8	Site S2. Moose Creek (PLMP 3.9). Looking at left bank.	9
Photo 9	Site S2. Moose Creek (PLMP 3.9). Looking at the right high bank.	10
Photo 10	Site S3. Tolsona Creek (PLMP 16.0). Looking upstream of bridge.....	11
Photo 11	Site S3. Tolsona Creek (PLMP 16.0). Looking downstream of bridge.....	11
Photo 12	Site S3. Tolsona Creek (PLMP 16.0). Looking at left bank.	12
Photo 13	Site S3. Tolsona Creek (PLMP 16.0). Looking across the proposed crossing towards the right bank.	12
Photo 14	Site S3. Tolsona Creek (PLMP 16.0). Looking at right bank.	13
Photo 15	Site S5. Little Woods Creek (PLMP 20.1). Looking upstream from highway.	14
Photo 16	Site S5. Little Woods Creek (PLMP 20.1). Looking at right bank.	14
Photo 17	Site S5. Little Woods Creek (PLMP 20.1). Looking at left bank.	15
Photo 18	Site S6. Tributary of Atlasta Creek (PLMP 23.9). Looking upstream.	15
Photo 19	Site S6. Tributary of Atlasta Creek (PLMP 23.9). Looking downstream.....	16
Photo 20	Site S6. Tributary of Atlasta Creek (PLMP 23.9). Looking at right bank.	16
Photo 21	Site S7. Tex Smith Lake Drainage (PLMP 26.8). Looking downstream from highway.	17
Photo 22	Site S7. Tex Smith Lake Drainage (PLMP 26.8). Looking upstream.....	17
Photo 23	Site S7. Tex Smith Lake Drainage (PLMP 26.8). Looking at right bank.....	18
Photo 24	Site S7. Tex Smith Lake Drainage (PLMP 26.8). Looking downstream.....	18
Photo 25	Site S8. Woods Creek (PLMP 34.5). Looking upstream.	19
Photo 26	Site S8. Woods Creek (PLMP 34.5). Looking upstream.	19
Photo 27	Site S8. Woods Creek (PLMP 34.5). Looking upstream.	20
Photo 28	Site S8. Woods Creek (PLMP 34.5). Looking at right bank.....	20
Photo 29	Site S8. Woods Creek (PLMP 34.5). Looking downstream.....	21
Photo 30	Site S8. Woods Creek (PLMP 34.5). Looking upstream.	21
Photo 31	Site S9. Mendeltna Creek (PLMP 35.8). Showing meandering bends at the proposed crossing site.	22
Photo 32	Site S9. Mendeltna Creek (PLMP 35.8). Meandering bends at the proposed crossing site.....	22
Photo 33	Site S9. Mendeltna Creek (PLMP 35.8). Upstream from bridge along the highway.	23
Photo 34	Site S9. Mendeltna Creek (PLMP 35.8). Looking at left bank adjacent to the highway bridge.....	24
Photo 35	Site S9B. Mendeltna Creek alternate site (PLMP 35.8). Looking downstream.....	25
Photo 36	Site S9B. Mendeltna Creek alternate site (PLMP 35.8). Looking towards right bank.	25
Photo 37	Site S9B. Mendeltna Creek alternate site (PLMP 35.8). Looking upstream from left bank..	26
Photo 38	Site S10. Cache Creek (PLMP 41.2). Looking downstream.....	26
Photo 39	Site S10. Cache Creek (PLMP 41.2). Looking upstream.	27
Photo 40	Site S10. Cache Creek (PLMP 41.2). Looking at right bank and creek bottom.	28
Photo 41	Site S10. Cache Creek (PLMP 41.2). Looking upstream.	29
Photo 42	Site S10. Cache Creek (PLMP 41.2). Looking upstream.	29
Photo 43	Site S11. Startup Creek (PLMP 64.8). Looking at left bank.	30
Photo 44	Site S11. Startup Creek (PLMP 64.8). Looking upstream.....	31
Photo 45	Site S11. Startup Creek (PLMP 64.8). Looking downstream.	32

Photo 46	Site S11. Startup Creek (PLMP 64.8). Looking at right bank from left bank.	33
Photo 47	Site S11. Startup Creek (PLMP 64.8). Looking at right high bank from left high bank.	33
Photo 48	Site S12. Caribou Creek (PLMP 75.7). Looking upstream.	34
Photo 49	Site S12. Caribou Creek (PLMP 75.7). Looking downstream.	34
Photo 50	Site S12. Caribou Creek (PLMP 75.7). Looking upstream (along alignment).	35
Photo 51	Site S12. Caribou Creek (PLMP 75.7). Looking at left high bank.	35
Photo 52	Site S12. Caribou Creek (PLMP 75.7). Looking at fractured rock on left bank terrace approximately 200 feet up river from the proposed crossing site.	36
Photo 53	Site S12. Caribou Creek (PLMP 75.7). Looking at bedrock on right bank approximately 300 feet up river from the proposed crossing site.	36
Photo 54	Site S12. Caribou Creek (PLMP 75.7). Looking upstream.	37
Photo 55	Site S12. Caribou Creek (PLMP 75.7). Bedrock along the left bank downstream of the proposed crossing site approximately 500 feet.	37
Photo 56	Site S12. Caribou Creek (PLMP 75.7). Bedrock along the left bank downstream of the proposed crossing site approximately 500 feet.	38
Photo 57	Site S12. Caribou Creek (PLMP 75.7). Bedrock along the left bank downstream of the proposed crossing site approximately 500 feet.	39
Photo 58	Site S13. Chickaloon River (PLMP 110.5). Looking at exposed bedrock and steep bluff along the left bank.	40
Photo 59	Site S13. Chickaloon River (PLMP 110.5). Looking upstream.	41
Photo 60	Site S13. Chickaloon River (PLMP 110.5). Looking downstream.	41
Photo 61	Site S13. Chickaloon River (PLMP 110.5). Looking downstream.	42
Photo 62	Site S13. Chickaloon River (PLMP 110.5). Looking upstream at left bank.	42
Photo 63	Site S14. Kings River (PLMP 117.9). Looking upstream.	43
Photo 64	Site S14. Kings River (PLMP 117.9). Looking downstream.	43
Photo 65	Site S14. Kings River (PLMP 117.9). Looking at left bank.	44
Photo 66	Site S14. Kings River (PLMP 117.9). Looking downstream towards right bank.	45
Photo 67	Site S14. Kings River (PLMP 117.9). Looking downstream.	45
Photo 68	Site S14. Kings River (PLMP 117.9). Looking downstream from terrace above right high bank.	46
Photo 69	Site S14. Kings River (PLMP 117.9). Boulders in terrace above right high bank.	47
Photo 70	Site S14. Kings River (PLMP 117.9). Right bank upstream of proposed crossing.	48
Photo 71	Site S14. Kings River (PLMP 117.9). Left bank upstream of proposed crossing site.	49
Photo 72	Site S15. Little Granite Creek (PLMP 124.3). Looking at left bank.	50
Photo 73	Site S15. Little Granite Creek (PLMP 124.3). Looking upstream.	51
Photo 74	Site S15. Little Granite Creek (PLMP 124.3). Looking downstream.	51
Photo 75	Site S15. Little Granite Creek (PLMP 124.3). Looking downstream.	52
Photo 76	Site S15. Little Granite Creek (PLMP 124.3). Looking towards right bank from on top of the bluff (approximately 60 to 80 feet above creek bottom).	53
Photo 77	Site S16. Granite Creek (PLMP 126.0). Looking at left bank.	54
Photo 78	Site S16. Granite Creek (PLMP 126.0). Looking upstream.	55
Photo 79	Site S16. Granite Creek (PLMP 126.0). Looking downstream.	55
Photo 80	Site S16. Granite Creek (PLMP 126.0). Looking downstream.	56
Photo 81	Site S16. Granite Creek (PLMP 126.0). Pictures of boulders (up to 40 inches in diameter) along right high bank.	56
Photo 82	Site S16. Granite Creek (PLMP 126.0). Pictures of boulders (up to 40 inches in diameter) along right high bank.	57
Photo 83	Site S17. Eska Creek (PLMP 128.0). Looking towards left bank.	58
Photo 84	Site S17. Eska Creek (PLMP 128.0). Looking towards left bank.	59
Photo 85	Site S17. Eska Creek (PLMP 128.0). Looking downstream.	60
Photo 86	Site S17. Eska Creek (PLMP 128.0). Looking downstream.	60
Photo 87	Site S17. Eska Creek (PLMP 128.0). Looking upstream.	61
Photo 88	Site S17. Eska Creek (PLMP 128.0). Looking upstream.	61
Photo 89	Site S17. Eska Creek (PLMP 128.0). Looking at left bank soil and cobbles in old stream bed.	62
Photo 90	Site S18. Moose Creek (PLMP 134.3). Looking upstream.	63
Photo 91	Site S18. Moose Creek (PLMP 134.3). Looking downstream.	63

Photo 92	Site S18. Moose Creek (PLMP 134.3). Looking at left bank from the right bank.	64
Photo 93	Site S18. Moose Creek (PLMP 134.3). Dense vegetation towards west ridge/bluff (beyond right bank).	65
Photo 94	Site S18. Moose Creek (PLMP 134.3). Gravel / cobbles observed in exposed bluff along west side slope (beyond the right high bank).	66
Photo 95	Site S18. Moose Creek (PLMP 134.3). Looking at creek and east ridge from on top of the west ridge.	67
Photo 96	Site S19. Carnegie Creek (PLMP 138.5). Looking downstream.	68
Photo 97	Site S19. Carnegie Creek (PLMP 138.5). Looking upstream.	68
Photo 98	Site S19. Carnegie Creek (PLMP 138.5). Looking across creek towards left bank.	69
Photo 99	Site S20. Wasilla Creek (PLMP 141.7). Looking upstream.	69
Photo 100	Site S20. Wasilla Creek (PLMP 141.7). Looking upstream.	70
Photo 101	Site S20. Wasilla Creek (PLMP 141.7). Looking downstream.	70
Photo 102	Site S20. Wasilla Creek (PLMP 141.7). Looking downstream.	71
Photo 103	Site S20. Wasilla Creek (PLMP 141.7). Looking downstream.	71
Photo 104	Site S20. Wasilla Creek (PLMP 141.7). Looking at right bank from left bank.	72
Photo 105	Site S21. Spring Creek (PLMP 147.2). Looking downstream towards area covered by wetland.	72
Photo 106	Site S21. Spring Creek (PLMP 147.2). Looking downstream of creek at area covered by wetland.	73
Photo 107	Site S21. Spring Creek (PLMP 147.2). Looking south in the vicinity of the creek / wetland.	73
Photo 108	Site S21. Spring Creek (PLMP 147.2). Looking at culvert outlet along Fireweed Drive frontage road.	74



Photo 1 Site S1. East Fork Moose Creek (PLMP 1.0). Looking across active channel from right high bank.



Photo 2 Site S1. East Fork Moose Creek (PLMP 1.0). Soil approximately 100 feet from right high bank.



Photo 3 Site S1. East Fork Moose Creek (PLMP 1.0). Looking upstream (difficult to see creek through the grass).



Photo 4 Site S1. East Fork Moose Creek (PLMP 1.0). Looking north (upstream at proposed crossing site).



Photo 5 Site S2. Moose Creek (PLMP 3.9). Looking upstream from proposed crossing site.



Photo 6 Site S2. Moose Creek (PLMP 3.9). Looking downstream from proposed crossing site.




Photo 7 Site S2. Moose Creek (PLMP 3.9). Looking at right bank.



Photo 8 Site S2. Moose Creek (PLMP 3.9). Looking at left bank.



Photo 9 Site S2. Moose Creek (PLMP 3.9). Looking at the right high bank.



Photo 10 Site S3. Tolsona Creek (PLMP 16.0). Looking upstream of bridge.



Photo 11 Site S3. Tolsona Creek (PLMP 16.0). Looking downstream of bridge.



Photo 12 Site S3. Tolsona Creek (PLMP 16.0). Looking at left bank.



Photo 13 Site S3. Tolsona Creek (PLMP 16.0). Looking across the proposed crossing towards the right bank.



Photo 14 Site S3. Tolsona Creek (PLMP 16.0). Looking at right bank.



Photo 15 Site S5. Little Woods Creek (PLMP 20.1). Looking upstream from highway.



Photo 16 Site S5. Little Woods Creek (PLMP 20.1). Looking at right bank.



Photo 17 Site S5. Little Woods Creek (PLMP 20.1). Looking at left bank.



Photo 18 Site S6. Tributary of Atlasta Creek (PLMP 23.9). Looking upstream.



Photo 19 Site S6. Tributary of Atlasta Creek (PLMP 23.9). Looking downstream.



Photo 20 Site S6. Tributary of Atlasta Creek (PLMP 23.9). Looking at right bank.



Photo 21 Site S7. Tex Smith Lake Drainage (PLMP 26.8). Looking downstream from highway.



Photo 22 Site S7. Tex Smith Lake Drainage (PLMP 26.8). Looking upstream.



Photo 23 Site S7. Tex Smith Lake Drainage (PLMP 26.8). Looking at right bank.



Photo 24 Site S7. Tex Smith Lake Drainage (PLMP 26.8). Looking downstream.



Photo 25 Site S8. Woods Creek (PLMP 34.5). Looking upstream.



Photo 26 Site S8. Woods Creek (PLMP 34.5). Looking upstream.



Photo 27 Site S8. Woods Creek (PLMP 34.5). Looking upstream.



Photo 28 Site S8. Woods Creek (PLMP 34.5). Looking at right bank.



Photo 29 Site S8. Woods Creek (PLMP 34.5). Looking downstream.



Photo 30 Site S8. Woods Creek (PLMP 34.5). Looking upstream.



Photo 31 Site S9. Mendeltna Creek (PLMP 35.8). Showing meandering bends at the proposed crossing site.



Photo 32 Site S9. Mendeltna Creek (PLMP 35.8). Meandering bends at the proposed crossing site.



Photo 33 Site S9. Mendeltna Creek (PLMP 35.8). Upstream from bridge along the highway.



Photo 34 Site S9. Mendeltna Creek (PLMP 35.8). Looking at left bank adjacent to the highway bridge.



Photo 35 Site S9B. Mendeltna Creek alternate site (PLMP 35.8). Looking downstream.



Photo 36 Site S9B. Mendeltna Creek alternate site (PLMP 35.8). Looking towards right bank.



Photo 37 Site S9B. Mendeltna Creek alternate site (PLMP 35.8). Looking upstream from left bank.



Photo 38 Site S10. Cache Creek (PLMP 41.2). Looking downstream.



Photo 39 Site S10. Cache Creek (PLMP 41.2). Looking upstream.



Photo 40 Site S10. Cache Creek (PLMP 41.2). Looking at right bank and creek bottom.



Photo 41 Site S10. Cache Creek (PLMP 41.2). Looking upstream.



Photo 42 Site S10. Cache Creek (PLMP 41.2). Looking upstream.



Photo 43 Site S11. Startup Creek (PLMP 64.8). Looking at left bank.



Photo 44 Site S11. Startup Creek (PLMP 64.8). Looking upstream.



Photo 45 Site S11. Startup Creek (PLMP 64.8). Looking downstream.



Photo 46 Site S11. Startup Creek (PLMP 64.8). Looking at right bank from left bank.



Photo 47 Site S11. Startup Creek (PLMP 64.8). Looking at right high bank from left high bank.



Photo 48 Site S12. Caribou Creek (PLMP 75.7). Looking upstream.



Photo 49 Site S12. Caribou Creek (PLMP 75.7). Looking downstream.



Photo 50 Site S12. Caribou Creek (PLMP 75.7). Looking upstream (along alignment).



Photo 51 Site S12. Caribou Creek (PLMP 75.7). Looking at left high bank.



Photo 52 Site S12. Caribou Creek (PLMP 75.7). Looking at fractured rock on left bank terrace approximately 200 feet up river from the proposed crossing site.



Photo 53 Site S12. Caribou Creek (PLMP 75.7). Looking at bedrock on right bank approximately 300 feet up river from the proposed crossing site.



Photo 54 Site S12. Caribou Creek (PLMP 75.7). Looking upstream.



Photo 55 Site S12. Caribou Creek (PLMP 75.7). Bedrock along the left bank downstream of the proposed crossing site approximately 500 feet.



Photo 56 Site S12. Caribou Creek (PLMP 75.7). Bedrock along the left bank downstream of the proposed crossing site approximately 500 feet.



Photo 57 Site S12. Caribou Creek (PLMP 75.7). Bedrock along the left bank downstream of the proposed crossing site approximately 500 feet.



Photo 58 Site S13. Chickaloon River (PLMP 110.5). Looking at exposed bedrock and steep bluff along the left bank.



Photo 59 Site S13. Chickaloon River (PLMP 110.5). Looking upstream.



Photo 60 Site S13. Chickaloon River (PLMP 110.5). Looking downstream.



Photo 61 Site S13. Chickaloon River (PLMP 110.5). Looking downstream.



Photo 62 Site S13. Chickaloon River (PLMP 110.5). Looking upstream at left bank.



Photo 63 Site S14. Kings River (PLMP 117.9). Looking upstream.



Photo 64 Site S14. Kings River (PLMP 117.9). Looking downstream.




Photo 65 Site S14. Kings River (PLMP 117.9). Looking at left bank.



Photo 66 Site S14. Kings River (PLMP 117.9). Looking downstream towards right bank.



Photo 67 Site S14. Kings River (PLMP 117.9). Looking downstream.



Photo 68 Site S14. Kings River (PLMP 117.9). Looking downstream from terrace above right high bank.



Photo 69 Site S14. Kings River (PLMP 117.9). Boulders in terrace above right high bank.



Photo 70 Site S14. Kings River (PLMP 117.9). Right bank upstream of proposed crossing.



Photo 71 Site S14. Kings River (PLMP 117.9). Left bank upstream of proposed crossing site.



Photo 72 Site S15. Little Granite Creek (PLMP 124.3). Looking at left bank.



Photo 73 Site S15. Little Granite Creek (PLMP 124.3). Looking upstream.



Photo 74 Site S15. Little Granite Creek (PLMP 124.3). Looking downstream.



Photo 75 Site S15. Little Granite Creek (PLMP 124.3). Looking downstream.



Photo 76 Site S15. Little Granite Creek (PLMP 124.3). Looking towards right bank from on top of the bluff (approximately 60 to 80 feet above creek bottom).



Photo 77 Site S16. Granite Creek (PLMP 126.0). Looking at left bank.



Photo 78 Site S16. Granite Creek (PLMP 126.0). Looking upstream.



Photo 79 Site S16. Granite Creek (PLMP 126.0). Looking downstream.



Photo 80 Site S16. Granite Creek (PLMP 126.0). Looking downstream.



Photo 81 Site S16. Granite Creek (PLMP 126.0). Pictures of boulders (up to 40 inches in diameter) along right high bank.



Photo 82 Site S16. Granite Creek (PLMP 126.0). Pictures of boulders (up to 40 inches in diameter) along right high bank.



Photo 83 Site S17. Eska Creek (PLMP 128.0). Looking towards left bank.



Photo 84 Site S17. Eska Creek (PLMP 128.0). Looking towards left bank.



Photo 85 Site S17. Eska Creek (PLMP 128.0). Looking downstream.



Photo 86 Site S17. Eska Creek (PLMP 128.0). Looking downstream.



Photo 87 Site S17. Eska Creek (PLMP 128.0). Looking upstream.



Photo 88 Site S17. Eska Creek (PLMP 128.0). Looking upstream.



Photo 89 Site S17. Eska Creek (PLMP 128.0). Looking at left bank soil and cobbles in old stream bed.



Photo 90 Site S18. Moose Creek (PLMP 134.3). Looking upstream.



Photo 91 Site S18. Moose Creek (PLMP 134.3). Looking downstream.



Photo 92 Site S18. Moose Creek (PLMP 134.3). Looking at left bank from the right bank.



Photo 93 Site S18. Moose Creek (PLMP 134.3). Dense vegetation towards west ridge/bluff (beyond right bank).



Photo 94 Site S18. Moose Creek (PLMP 134.3). Gravel / cobbles observed in exposed bluff along west side slope (beyond the right high bank).



Photo 95 Site S18. Moose Creek (PLMP 134.3). Looking at creek and east ridge from on top of the west ridge.



Photo 96 Site S19. Carnegie Creek (PLMP 138.5). Looking downstream.



Photo 97 Site S19. Carnegie Creek (PLMP 138.5). Looking upstream.



Photo 98 Site S19. Carnegie Creek (PLMP 138.5). Looking across creek towards left bank.



Photo 99 Site S20. Wasilla Creek (PLMP 141.7). Looking upstream.



Photo 100 Site S20. Wasilla Creek (PLMP 141.7). Looking upstream.



Photo 101 Site S20. Wasilla Creek (PLMP 141.7). Looking downstream.



Photo 102 Site S20. Wasilla Creek (PLMP 141.7). Looking downstream.



Photo 103 Site S20. Wasilla Creek (PLMP 141.7). Looking downstream.



Photo 104 Site S20. Wasilla Creek (PLMP 141.7). Looking at right bank from left bank.



Photo 105 Site S21. Spring Creek (PLMP 147.2). Looking downstream towards area covered by wetland.



Photo 106 Site S21. Spring Creek (PLMP 147.2). Looking downstream of creek at area covered by wetland.



Photo 107 Site S21. Spring Creek (PLMP 147.2). Looking south in the vicinity of the creek / wetland.



Photo 108 Site S21. Spring Creek (PLMP 147.2). Looking at culvert outlet along Fireweed Drive frontage road.